

Copy to manufacturer

ACCIDENT BRIEF

Cent.
Trans.
Foreign ✓

Phase of Flight normal flight Accident No. 47-11-1-501
 Accident I no further info MSB-17G AC Ser. No. 43-39338
 Air Force or Command AFE Station Roseboro, Va Damage 1st A/C work
 Mission light training Injury 4 1 1 1 1 Total in A/C 5
 (XC) 1 2 3 4 5
 TMS 2nd A/C Damage 2nd A/C Day Night ✓ Flight Ref AI
 Place of Accident unknown - A/C missing in flight
 Total Aircraft Hours unknown Altitude of Flight unknown
 Formation no formation Weather 8-Clouds normal flight

-- 1st Pilot --

Total hours 2971:00 Total Instr. Hours 31:00
 Hours this type 430:00 Instr. last 6 mos. 1:55
 Hours this model 430:00 Instr. last 30 da. 1:20
 Hours last 30 da. 24:45 Night last 6 mos. 10:00
 Combat hours (Pilot & Co-Pilot) 75:00 Night last 30 da. 1:00

UR submitted on Part No. None Submitted

CAUSE FACTORS

Pers	UNSAFE ACTS			UNSAFE CONDITIONS					UNDET
	Major	Specific	Viol.	Major	Specific	Minor	Defects	Seq	
0	1	1	2	1				3	X

Additional Information and Recommendations (Include Design Characteristics)

(1) That radio operators maintain continual communication with ground stations as a safety factor in the possible event of an emergency (2) That night flights be attempted in ETO only or in mild instrument weather

Evaluated By: Cisler Briefed By: Cisler
 Logged By:

(NARRATIVE ON REVERSE SIDE)